

# General Environmental Incident Summary

**Incident:** 218      **Date/Time Notice:** 10/27/1994      **DEM Incident No:**

**Responsible Party:** American Crystal Sugar Company

**Date Incident:** 10/26/1994      **Time Incident:**      **Duration:**

**County:** Pembina      **Twp:** 159      **Rng:** 51      **Sec:** 14      **Qtr:** SE

**Lat:** 48.59303      **Long:** -97.17905      **Method:** Derived from TRS

**Location Description:** 8152 County Highway 44 North, Drayton, ND

**Submitted By:**

**Affiliation:**

**Address:**

**City:**

**State:**

**Zip:**

**Received By:**

**Contact Person:** Ron Koester  
8152 County Highway 44 North  
PO Box 190  
Drayton, ND 58225-0190

**Distance Nearest Occupied Building:**

**Type of Incident:** HYDROCARBON

**Description of Released Contaminant:** Transformer Oil

**Volume Spilled:** 100.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:**

**Reported to NRC:** No

**Cause of Incident:**

NON PCB TRANSFORMER. WILL REMOVE SOIL.

**Risk Evaluation:**

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

**Wastes Disposal Location:**

**Agencies Involved:**

